



**ALTRINCHAM RETAIL PARK, PROPOSED EASTERN EGRESS,  
SECTION 278 WORKS  
ITEMS OUTSIDE THE SCOPE OF THE  
COMBINED STAGE 1 AND 2 ROAD SAFETY AUDIT**

Ref	Location	Comment/Observation	Suggestion
1	Internal Road	Arrows are shown on the drawing and it appears to suggest they are existing arrows. However, no arrows exist.  It is also observed that arrows do not highlight the proposed access.	Review and amend accordingly.
2	Internal layout.	The existing tactile paving are 'red' which are provided for controlled crossings. In addition, some of the dropped crossings/tactile layouts are inappropriate i.e. high kerb upstands, no crossing on opposite side.  	Observation.
3	George Richards Way – West-side of proposed access.	Existing gully surround is damaged.  	Report to Trafford Council.
4	Proposed egress.	It may be worth providing 'No Entry' signs. Whilst the alignment, give-way road markings and the traffic island should be self-explanatory and enforcing. However, the signs may provide added benefits.	Review and amend accordingly.
5	George Richards Way	There is a sign missing from a post located to the west of the proposed egress.	Report to Trafford Council.
6	George Richards Way	It would be prudent to provide a 'NEW ROAD LAYOUT AHEAD' sign.	Review and amend accordingly.

**Mark Hedley**  
Road Safety Audit Team Leader  
23 August 2019